

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11005</i>	LOCATION <i>3132 - Land Lee's Way</i>			
DATE <i>12/29/42</i>	PURPOSE <i>General repairs to building</i>			
ZONE <i>1</i>	OWNER <i>Roy Dreyton -</i>			
	ARCH'T. <i>Owner</i>			
	CONTR. <i>Owner</i>			
VAL <i>300⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
4/6/43	1 ST /WSP. Concrete Foundation for wing on North side of rear moved back 3 ft from line. O.K. A.W. Campbell
4/6/43	2 ND /WSP. Frame for Remodeled old wing O.K. A.W. Campbell.
4/12/43	3 RD /WSP. Patching of interior Sathing ^{OK} A.W. Campbell
4/14/43	Made dup of bus Hall heater & run below floor to chimney ^{OK}
9/22/43	4 TH /WSP. Alterations & Repairs to DWG. ✓
9/22/43	COMPLETE AND O. K. Alden W. Campbell INSPECTOR