

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10434</i>	LOCATION <i>1823-T. St.</i>			
DATE <i>6/8/42</i>	PURPOSE <i>Repairs to div. due to fire</i>			
ZONE	OWNER <i>J. Burnett</i>			
	ARCH'T. <i>Chas. Vanina</i>			
	CONTR. <i>Chas. Vanina</i>			
VAL. <i>990⁰⁰</i>	STORIES <i>-</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
6/9/42	Made Partial Inspection of Repairs to
	2-Story 4 Flat Bldg. recently damaged by fire
	All burned timbers, etc. to be replaced
	with new materials A. W. Campbell
	COMPLETE AND O. K. INSPECTOR