

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-2933</i>	LOCATION <i>3224 - Stockton Blvd</i>			
DATE <i>6/17/35</i>	PURPOSE <i>Make addit. to phone post</i>			
ZONE <i>5</i>	OWNER <i>E. S. Helen</i>			
ARCH'T <i>Sam Pellet</i>	CONT'R <i>Owner</i>			
VAL. <i>2000</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
6/13/35	Made Francis Jump 2 Addition to Service Station. O.K. <i>Atk. [unclear]</i>
8/9/35	4 th Jump Addition to Service Station. Combined O.K.
8/17/35	COMPLETE AND O. K. <i>Atk. [unclear]</i> INSPECTOR