

BIBI 7162-163-2

| BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | | | | \$26.00 |
|--|----------|-------------------------------------|----------|-----------------|---------------|---------|
| TYPE BUILDINGS | | | | | Double Fee | |
| PERMIT NO. | | | | | | |
| E-3817 | LOCATION | 4993 - Stockton Blvd. | | | | A-1 |
| DATE | PURPOSE | Remodel exist. bldg. to office & | | | | |
| May 6-63 | OWNER | Sacto. Employes Ent. /retail store. | | | | |
| ZONE | ARCH'T | George Higgins 2321 - P Street | | | | |
| C-2 | CONT'R | Owner | Same | GL 2-5021 | | |
| VAL. | \$2,000. | STORIES | ROOMS | APTS. | SIZE | |
| | | 1 | | | 1,720 sq. ft. | |
| INSP. | DATE | BLDG. TYPE | V-no hr. | OCCUPANCY GROUP | F-2 | |
| FORM | | | | | | |
| JOIST | | | | | | |
| FRAME SHEET ROCK | 5-14-63 | Larsen | | | | |
| FINAL | 5-23-63 | E. Larsen | | | Pat Com Rep | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 5-7-63 | Pt Electric meters installed. Part joints |
| 5-19-63 | ready for frame Pt of 4-6-63 |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |

