

Elenor Fernandez

2320 Fruitridge  
Sacto. CAScope of Work

- 1- Reroof FRONT Slope 25 Yr Comp To Match 750
- 2- Replace HVAC UNIT
- 3- Elec MIN Repair
- 4- Elec FINISH
- 5- Remove & Replace INSULATION COMP Ceiling R-38 wall R-18
- 6- Plumbing FINISH COMP
- 7- Drywall COMP
- 8- Cabinets COMP
- 9- INT PAINT
- 10- Flooring
- 11- Replace INT DOORS & TRIM
- 12- Install Retro FIT WINDOWS

Total      \$ 41,500

Roofing

