

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS Lot 150 W + K # 33

PERMIT NO. 3549	LOCATION 520 PALM WAY <small>PALM WAY COLONIAL WAY PICA WAY F 521</small>
DATE OCT 15, 1928	PURPOSE 1-Story frame Stucco 5-Rm Det. + Garage
ZONE 2nd RES	OWNER N. H. LUND - 3300 Curtis Way
	ARCHT
	CONTR OWNER
	VAL. 5000⁰⁰ STORIES 1 SIZE 37'-6" x 35'

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	8x12
	Beams and Girders						Fireplace	8x12
Int Wall	Studs and Columns						Fire Place	
	Bridging Fire Stops						Gas Water Heater	
Piers	Fire Escape Stand Pipes						Heater Closet	
	Metal Lath						Furnace	Window Courts
	Stairs						Boiler Room	
							Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
10/17/28	1 ST /NSP. FORMS IN PLACE O.K. A.W. Campbell
	<p data-bbox="336 889 520 944">COMPLETED AND O. K.</p> <p data-bbox="1251 922 1419 944">INSPECTOR</p>