

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS Also No. 5425-2<sup>nd</sup> Flr

PERMIT NO. <i>A-504</i>	LOCATION <i>2632-55<sup>th</sup> St.</i>	
DATE <i>Apr. 10-31</i>	PURPOSE <i>Add two Bed Rm. Rear of 3 Rm. Ho.</i>	PHONES
ZONE <i>r-Fam</i>	OWNER <i>Chris Day</i>	
	ARCH'T <i>John H. Loddick</i>	
	CONT-R	

VAL.

*500<sup>00</sup>*

STORIES

*1*

ROOMS

APTS.

SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
4/13/33	1 <sup>st</sup> MSP. Form for Addition to Duty <sup>OK</sup> A.W. Campbell noted that Owner's No. 1 Number should be changed
	to 5475-2 <sup>nd</sup> No. as front door face 2 <sup>nd</sup> key Owner agreed to change House Number in same.
4/27/33	2 <sup>nd</sup> MSP. Frame in place <sup>OK</sup> A.W. Campbell
5/2/33	3 <sup>rd</sup> MSP. lat. frame <sup>OK</sup> A.W. Campbell
	COMPLETE AND O. K.
	INSPECTOR