

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 9063	LOCATION 1421-13 ^{1/2}
DATE 1/19/32	PURPOSE Impr. Rep. Fire Loss.
ZONE	OWNER O Coffin
VAL. 850 —	ARCH'T
STORIES	ROOMS
APTS.	SIZE
Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK--REMARKS
1/13/27	2 ND / N.S.P. Frame In Repair to 3-Struc Dole damaged by fire. All burned timbers
	replaced with new material. 4" x 4" x 8"
	T.C. Vent Flues installed low gas ^{Mr Campbell} venting
11-27-27	3 RD / N.S.P. Metal Lath on both sides of T.C. Vents OK Mr Campbell
	Notified owner re: rotten timbers. Front porch will have to be strengthened & repaired M.C.
	COMPLETE AND O. K. INSPECTOR