

Q183 7368-372

| | | | | | |
|------------------|---------|--|-----------------|-------------------------------|-----|
| Lot 79 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$43.00 | | | |
| Blk. 273 | | TYPE BUILDINGS: | | | |
| Monte Vista Sub. | | | | | |
| PERMIT NO. | | LOCATION | | | A-1 |
| F-2632 | | 5954 - 2nd Avenue | | | |
| DATE | PURPOSE | Const. dwlg. & att. gar. | | | |
| Dec 21-65 | OWNER | Mel Longshore 2890-Del Paso Blvd. | | | |
| ZONE | ARCH'T | | | | |
| R-1 | CONT'R | Owner same 927-0307 | | | |
| VAL. \$11,100. | STORIES | ROOMS | APTS. | 273-gar. SIZE 1278 sq. ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 1-6-66 | Hammers | | | |
| JOIST | 1-14-66 | Callaway | | | |
| FRAME | 2-18-66 | Callaway | | | |
| SHEET ROCK | 3-25-66 | Numbers | | | |
| FINAL | 4-12-66 | Numbers | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|---|
| 2-15-66 | P.T. Firewall - hardware did not in. Lassen |
| 4-7-66 | Pt Terminal SR rails in fireplace |
| | must be spotted. Hammers |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |