

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS *R14-F415-436*

PERMIT NO. <i>A-4741</i>	LOCATION <i>615 K Street</i>			
DATE <i>8-28-36</i>	PURPOSE <i>remodel Theatre Bldg</i>			
ZONE	OWNER <i>Fox Capitol Theatre</i>			
	ARCH'T			
	CONT'R <i>Salih Bros.</i>			
VAL. <i>\$25,000.00</i>	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	INSPECTOR		
FORM				
JOIST				
FRAME				
LATH				
FINAL				

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
COMPLETE AND OK	INSPECTOR

MODEL CAPITAL THEATER

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. A-4741	LOCATION 615-R St.
DATE 8/28/36	PURPOSE Remodel old Theatre Bldg
ZONE Gen. Com.	OWNER Fox Capital Theatre
	ARCH'T. J. Loyd Condrick SAN FRANCISCO
	CONT'R. Salih Bros. SAN FRANCISCO

VAL. 25,000⁰⁰	STORIES	ROOMS	APTS.	SIZE
---------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK-REMARKS
9/16/36	Made Vertical Insp. Contractor now tearing out. int and
7/23/36	removing debris from Basement. A.W. Campbell
10/1/36	1 ST HSP. Forms for Redup Conc Footings & Structure
10/8/36	Redup Conc Lintel etc O.K. A.W. Campbell
10/15/36	2 ND HSP. Forms A.W. Campbell
12/23/36	3 RD HSP. Metal Lath Ceiling O.K. A.W. Campbell
3/16/37	3 RD HSP. Metal Lath Ceiling & Lathwork Note: Stand Pipe to be installed in stairway entrance to 3 rd floor. 3 RD HSP. Metal Lath Walls & Ceiling Lobby 1 ST & 2 ND Stg. O.K. A.W. Campbell
3/16/37	4 TH HSP. Remodeling & Alterations Complete O.K.
3/16/37	COMPLETE AND O. K. <i>Aldred W. Campbell</i> INSPECTOR