

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

Card 2

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA 6-S	FINAL INSPECTIONS	
		2001 Point West Way						BUILDING BY	
LEGAL DESCRIPTION		OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE		DATE		
		B-2	III-1HR		3				
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	
GEN. CONTR.								DATE	
ELEC. CONTR.								PLUMBING BY	
PLBG. CONTR.								DATE	
MECH. CONTR.								MECHANICAL BY	
ARCH. ENGR.								DATE	
OWNER								CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	
								DATE	
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:-

PERMIT NO. S.P. -		MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE		PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
VALUATION \$		INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$		JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$		REMARKS AND/OR VARIANCES			
\$					
\$					
TOTAL FEES \$					

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
11/1/77	B. \$ 1250.00	E-8773 \$ 40.00	Planter retaining wall at restaurant bldg	Red Lion Motor Inn	M. Daniels Const	Thompson	5-17-78
4/5/78	P. \$ 3500.00	F-2675 \$ 78.00	Installation of addition water heater for motor inn-comm	Red Lion Motor Inn	ABC Plumbing	5-17-78	5-17-78
8/31/78	E. \$ 200.00	G-8312 \$ 20.00	Install power pole for const. Trailer	Red Lion	Thundersbird Elec	Syllaasen	9/5/78
1/19/79	E. \$ 50.00	G-597 \$ Gratis	Install circuits for two detached pole signs	Red Lion Motor Inn	Owners		
1/18/79	Sign \$ 500.00	S-9419 \$ 20.00	Sign-comm	Red Lion Motor Inn	Owner	Treuer	5-7-80
1/18/79	Sign \$ 500.00	S-9420 \$ 20.00	Sign-comm	Red Lion Motor Inn	Owner	Treuer	5-7-80
7/31/79	P. \$ 6700	G7346 \$140	Irrigation for guested Lion wing Comm	same	owner	DeGruy	9-13-79
9/29/80	B \$3,000	H-7262 \$80.00	Repair of fire damage Sheetrock replacement	Thunderbird/Red Lion Motor Inns	Owner		
1-12-82	BME \$450000	I 1011 \$1432	Int. Remodel	Red Lion Motor Inns	Same	Head	3-8-83

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-8773	R 500 F 003	G7346	R584 F030-31	E-8773	R 525 F 220	G 1346	R699 F 62
F-2675	R 519 F 250			F-2675	R 525 F 220		
E-8773	R 525 F 220	G 1346	R699 F 62	E-8773	R 525 F 220	G 1346	R699 F 62
F-2675	R 525 F 220	G 1346	R699 F 62	F-2675	R 525 F 220	G 1346	R699 F 62
F-8312	R536 F516	H-7262	R641 F 419	F-8312	R536 F516	H-7262	R641 F 419
G-597	R522 F 296	F 1011 C	R 704 F 347-356	G-597	R522 F 296	F 1011 C	R 704 F 347-356
S-9419	R522 F 296			S-9419	R522 F 296		
S-9420	R522 F 296			S-9420	R522 F 296		