

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS	
LEGAL DESCRIPTION						OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		
GEN. CONTR.								BUILDING BY	DATE
ELEC. CONTR.								ELECTRICAL BY	DATE
PLBG. CONTR.								PLUMBING BY	DATE
MECH. CONTR.								MECHANICAL BY	DATE
ARCH. ENGR.									
OWNER								CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED

NATURE OF WORK:-

PERMIT NO. S.P. -		<b>MICROFILM RECORD</b>			
ISSUED BY					
ISSUANCE DATE					
VALUATION	\$	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
R.D.F. FEE	\$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
S.M.I. FEE	\$	JOB FILE	REEL NO.	FRAME NO:-	TO
PLAN CK. FEE	\$	<b>REMARKS AND/OR VARIANCES</b>			
SEWER INCL. FEE	\$				
PERMIT FEE	\$				
TOTAL FEES	\$				

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
10/8/63	Bldg. \$500.00	E-5258 \$5.00	Complete dwlg. started in County/54tsq.ft.	A. Cummins	Owner	Barbato	12/10/64
5/11/79	B. \$ 1500.00	G-4328 \$ 30.00	Repair sheetrock on ceiling-Repair dryrot on rather ends- Replace 2 windows- as per Housing.	Cummins	Ray Kirk	Wilson	5-15-79
				Same	2530 Cordova Lane		
					R.C. 95670		

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-5258	R-130 F-444				
E-5258	521 F490 F.M.A.C.				
G-4328	5370 F269				
(14328	521 F068				