

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>A-4526</b>	LOCATION <b>432 San Antonio Way</b>
DATE <b>7/2/36</b>	PURPOSE <b>Erect new dwlg &amp; garage</b>
ZONE <b>2-Fam</b>	OWNER <b>Klein Realty Co.</b>
VAL. <b>3800</b>	ARCH'T. <b>Klein Realty</b>
	CONTR. <b>Klein Realty 807-JR</b>
	STORIES <b>1</b>
	ROOMS <b>5</b>
	APTS. <b>1</b>
	SIZE <b>duplex</b>

LIGHT SHAFTS		ELEVATOR SHAFTS	Area 1100'² @ \$300-
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
8/17/36	2 <sup>ND</sup> / NSP. Frame in place <sup>OK</sup> A.W. Campbell
8/21/36	3 <sup>RD</sup> / NSP. INT. LATH <sup>OK</sup> A.W. Campbell
COMPLETE AND O. K.	INSPECTOR