

141 Commerce Circle

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
1-7-75	Bldg. \$13,500.	e-129 \$109.	Reroof <del>Dwelling</del>	The Goodyear Tire Akron Ohio	Roofers Inc P.O.Box 28006	<i>Hammond</i>	<i>8/10/76</i>
6/23/77	E. \$ 12,160.00	E-4632 \$ 148.00 <i>G-2591</i>	New Electrical service Comm	Goodyear Tire & Rubber Same	Ray O Cook 5534 Elvas Ave.	<i>Clark</i>	<i>11/14/77</i>
8/22/77	BMPE \$16,000.	E-6663 \$169. <i>C-2216</i>	Int. office & storage mezz in warehouse Bldg.	Goodyear Tire & Rubber Co. 141 Commerce	Golden State Bldg. 3849 Hollister Ave Carmichael, CA 95608	<i>Clark</i> <i>Nystrom</i> <i>Nystrom</i> <i>Hammond</i>	<i>10/7/77</i> <i>10/28/77</i> <i>10/28/77</i> <i>10-7-77</i>
11/29/67	B \$600.00	F-9114 \$10	Repair cracked beam in retread plant	Goodyear Tire	J. E. McDaniels	<i>Chapin</i>	<i>1/17/68</i>
10-3-80	Bldg. \$45,000	H-7393 \$422	Structual repair to tire recapping Bldg.	North Sacto Land	Douglas Const 1021 El Monte Av	<i>Hammond</i> <i>Hammond</i> <i>Hammond</i>	<i>1/9/80</i> <i>1/9/80</i> <i>1/9/80</i>

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
C-129	R402F639	F-9114	R229-F498		
<i>C-129</i>	<i>R452F572</i>	F-9114	<i>R490-F415 final</i>		
E-4632	<i>R485F568 &amp; plan</i>	H-7393	<i>R641F452-463</i>		
E-6663	<i>R491F483</i>	<i>H-7393</i>	<i>R656F154-153 final</i>		
<i>E-6663</i>	<i>R491F484 - 465-plan</i>				
<i>E-4632</i>	<i>R512F245</i>				
<i>E-6663</i>	<i>R512F244</i>				

