

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4877</i>	LOCATION <i>976 - Perkins Way.</i>
DATE <i>3/1/48</i>	PURPOSE <i>new dwlg & gar</i>
ZONE <i>r-7am</i>	OWNER <i>Dorothy Fitzgerald Henderson</i>
VAL. <i>4000⁰⁰</i>	CONTR. <i>Wright Henderson</i>
	STORIES <i>1</i>
	ROOMS <i>5</i>
	APTS. <i></i>
	SIZE <i></i>

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1050⁰⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>302</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
3/6/40	1ST HSP. Forme ^{OK} replaced <i>RH Campbell</i>
3/26/46	2 ND HSP. Frame ^{OK} " " <i>RH Campbell</i>
	<p data-bbox="315 922 467 967">COMPLETE AND O. K.</p> <p data-bbox="1278 938 1429 960">INSPECTOR</p>