

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4877</i>	LOCATION <i>976 - Perkins Way.</i>
DATE <i>3/1/48</i>	PURPOSE <i>new dwlg &amp; gar</i>
ZONE <i>r-7am</i>	OWNER <i>Dorothy Fitzgerald Henderson</i>
VAL. <i>4000<sup>00</sup></i>	CONTR. <i>Wright Henderson</i>
	STORIES <i>1</i>
	ROOMS <i>5</i>
	APTS. <i></i>
	SIZE <i></i>

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1050<sup>00</sup></i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>302</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
3/6/40	1ST/HSP. Forme <sup>OK</sup> replaced <i>RH Campbell</i>
3/26/46	2 <sup>ND</sup> HSP. Frame <sup>OK</sup> " " <i>RH Campbell</i>
	<p>COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span></p>