

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA		FINAL INSPECTIONS	
		2711 Bridgeford Drive				A-6			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	
Northgate Unit #9 Lot 1161									
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		
GEN. CONTR. Owner									BUILDING BY
ELEC. CONTR.									Riolo
PLBG. CONTR.									8-7-70
MECH. CONTR.									ELECTRICAL BY
ARCH. ENGR.									DATE
OWNER Taylor-Mazza, Inc.			P.O. Box 28236						PLUMBING BY
CONST. LOAN LENDER									DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	CERTIFICATE OF OCCUPANCY
						504 Gar. 1,200 sq.ft.			ISSUED BY
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	CENSUS TRCT. NO.	EXISTING BLDG'S SAME LOT	DATE

NATURE OF WORK:- Const. dwelling and garage MP #3-3

PERMIT NO. S.P. - G-6787	MICROFILM RECORD		
ISSUED BY	PLANS AND APPLICATION	REEL NO. 281	FRAME NO:- 216 TO
ISSUANCE DATE May 13-70	INSPECTION RECORD	REEL NO. 11 F005	FRAME NO:- 006 Contm
VALUATION \$ 18,400	JOB FILE	REEL NO.	FRAME NO:- TO
R.D.F. FEE \$			
S.M.I. FEE \$			
PLAN CK. FEE \$			
SEWER INCL. FEE \$			
PERMIT FEE \$	REMARKS AND/OR VARIANCES		
\$	Form: 6-3-70 Calloway		
\$	Frame: 6-24-70 Riolo		
TOTAL FEES \$ 71	Sheet Rock: 7-2-70 Hammons		