

R 281 F575

| | | | | | |
|----------------------|---|--|-----------------|------------|-------------------------------|
| Lot 687 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$62.00 |
| Southgate Meadows #8 | | TYPE BUILDINGS | | | R-2-59 F572-576-Plan |
| PERMIT NO. | | | | | |
| G-6934 | LOCATION 7732 - Millroy Way | | | A-5 (49) | |
| DATE | PURPOSE Const. dwelling & att. gar. | | | MP 1001 LB | |
| May 22-70 | OWNER Banderas, Inc. 2777 Alvarado S, Leandro | | | | |
| ZONE | ARCH'T | | | | |
| R-1 | CONTR Besco Builders, Inc. same 483-4300 | | | | |
| VAL. \$15,600. | | STORIES | ROOMS | APTS. | 340-gar. SIZE 1,032-sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | | PHONE (O) (C) |
| FORM | 10-9-70 | Summers | | | |
| JOIST | | | | | |
| FRAME | 7-2-70 | Coont | | | |
| SHEET ROCK | 7-14-70 | Wardens | | | |
| FINAL | 8-13-70 | E. Hansen | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 5-1-70 | OK not ready <i>R. B. B.</i> |
| 6-11-70 | OK slab - <i>Hammers</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |