

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B-9935</b>	LOCATION <b>857 - Swanton 10n</b>
DATE <b>1/31/42</b>	PURPOSE <b>Erect new dwlg.</b>
ZONE	OWNER <b>Ralph Fentado J.</b>
	ARCH'T.
	CONTR. <b>Joe Nevis.</b>

VAL. <b>5000<sup>00</sup></b>	STORIES <b>1</b>	ROOMS <b>5</b>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<b>Area</b> <b>1340<sup>sq</sup></b> <b>@ 350</b>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
2/10/42	1 <sup>ST</sup> /NSP. Forms in place <sup>OK</sup> A W Campbell
4/9/42	2 <sup>ND</sup> /NSP. Frame . . . <sup>OK</sup> A W Campbell
5/1/42	3 <sup>RD</sup> /NSP. INT & EXT LATH <sup>OK</sup> A W Campbell
7/15/42	4 <sup>TH</sup> /NSP. Arch & Garage Completed <sup>OK</sup>
7/15/42	<p>COMPLETE AND O. K. <i>Alfred W Campbell</i> INSPECTOR</p>