

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10786</i>	LOCATION <i>2671-13th St.</i>			
DATE <i>10/15/42</i>	PURPOSE <i>General repairs to dwg</i>			
ZONE	OWNER <i>W. C. Miller</i>			
	ARCH'T. <i>J. Paul Howell</i>			
	CONTR. <i>J. Paul Howell</i>			
VAL. <i>175⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
10/20/42	2 ND /HSP. Frame for Interior Alterations to Divly. O.K. A.W. Campbell.
10/20/42	3 RD /HSP. INT LATH (SEARCHING) ^{OK} A.W. Campbell.
	<p>COMPLETE AND O. K. INSPECTOR</p>