

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 3771 Erlwin Circle		INSPECTION AREA 1	
LEGAL DESCRIPTION Lot 1090 River Park #8					
GEN. CONTR.		WOODSON HOMES		3333 W. ST.	
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER		William L. Byn		5241 Moddison	
CONST. LOAN LENDER					
TITLE AND NAME		ADDRESS		CITY LIC. NO.	
WOODSON HOMES		3333 W. ST.		GL2-2737	
ELECTRICAL BY		ELECTRICAL BY		DATE	
PLUMBING BY		PLUMBING BY		DATE	
MECHANICAL BY		MECHANICAL BY		DATE	
CERTIFICATE OF OCCUPANCY		ISSUED BY		DATE	
		Berry		11/14/58	

BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOMS	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE
			1	5	560-gar.	1,075 sq. ft.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED

NATURE OF WORK: Const. dwelling & at. garage

PERMIT NO. S.P. - C-9922		ISSUED BY	
ISSUANCE DATE		9/29/58	
VALUATION		\$ 10,600.00	
R.D.F. FEE	\$	INSPECTION RECORD	REEL NO. 47
S.M.I. FEE	\$	FRAME NO. 387	TO 397
PLAN CK. FEE	\$	JOB FILE	REEL NO. TO
SEWER INCL. FEE	\$	REEL NO. TO	FRAME NO. TO
PERMIT FEE	\$ 31.00	REMARKS AND/OR VARIANCES	
TOTAL FEES	\$	R 492R 576 - DWELLING	

MICROFILM RECORD