

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT No. <i>A-1306</i>	LOCATION <i>4624 - UTA.</i>
DATE <i>1/15/34</i>	PURPOSE <i>Add to basement &amp; Bed Room</i>
ZONE <i>2-Fam.</i>	OWNER <i>Bauney H. J.</i>
	ARCH'T <i>" "</i>
	CONT-R <i>" "</i>
	PHONES

VAL. <i>350<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK—REMARKS
1/15/34	1 <sup>st</sup> HSP. Forms for 8' Beams. Walls and exterior walls placed - to side of Dory OK AW Campbell
1/23/34	2 <sup>nd</sup> HSP. Frame for additional beams OK AW Campbell
1/24/34	3 <sup>rd</sup> HSP. INT. LATH INC. PARTING. <sup>OK</sup> AW Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="325 849 476 896">COMPLETE AND O. K.</span> <span data-bbox="1126 875 1292 901">INSPECTOR</span> </div>