

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> <i>9073</i>	<b>LOCATION</b> <i>1913 Pk.</i>		
<b>DATE</b> <i>1/24/34</i>	<b>PURPOSE</b> <i>Ta. Edmore</i>		<b>PHONES</b>
<b>ZONE</b> <i>Mt. Fern</i>	<b>OWNER</b> <i>Peron</i>		
	<b>ARCH'T</b>		
	<b>CONT-R</b> <i>Frank Gill</i>		

<b>VAL.</b> <i>166 -</i>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
-----------------------------	----------------	--------------	--------------	-------------

<b>Light Shafts</b>		<b>Elevator Shafts</b>	
<b>Vent Shafts</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector</b>		<b>Sprinkler System</b>	
<b>Lath</b>		<b>Gas Vents</b>	
<b>Fire Escapes</b>		<b>Chimneys</b>	
<b>Stand Pipes</b>		<b>Skylights</b>	

DATE	CONDITION OF WORK—REMARKS
1/17/32	Re Shingling of Roof of Dairy Completed OK A.W. Campbell
1/17/32	COMPLETE AND O.K. <i>A.W. Campbell</i> INSPECTOR