

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS		
		3149 Bridgeford Drive					A-6			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
Larchmont Northgate #1 Lot43									Hammons	8-15-68
TITLE AND NAME			1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
Larchmont Northgate										
GEN. CONTR.	Larchmont Northgate									
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER	Larchmont Northgate #1								CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	GAR. AREA	C.S.D.	C.I. CASE		
					475 GAR	1382 sq ft				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED	
			R-1							

NATURE OF WORK:- Const. dwelling and garage Plan 84

PERMIT NO. S.P. - F-9285	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 231	FRAME NO:- 274	TO
ISSUANCE DATE 1-5-68	INSPECTION RECORD	REEL NO. 101592	FRAME NO:- 593	COMDURA
VALUATION \$ 13,600	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$				
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$	REMARKS AND/OR VARIANCES			
\$	Form: 1-22-68 Chapin			
\$	Frame: 3-19-68 Chapin			
TOTAL FEES \$	Sheet Rock: 3-25-68 Chapin			