


Lat 42 BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

Sandier Vint 21 TYPE BUILDINGS

PERMIT NO. <i>B-7081</i>	LOCATION <i>954 - Perkins Way</i>
DATE <i>12/2/40</i>	PURPOSE <i>Erect new dwlg & gar</i>
ZONE <i>-</i>	OWNER <i>N. H. Lund</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>500.00</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
--------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1234 ft</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 352</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12/5/41	1 ST / NSP. Forms in place ^{OK} A.W. Campbell
1/14/42	2 ND / NSP Frame ^{OK} A.W. Campbell
1/28/42	3 RD / NSP. INT & EXT LATH ^{OK} A.W. Campbell
4/10/42	4 TH / NSP. Dully & Curage Completed ^{OK}
4/10/42	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O. K. <div data-bbox="482 860 1032 946" style="text-align: center;">  </div> INSPECTOR </div>