

Q181 7248

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> F-2368		<b>LOCATION</b> 2844 - San Luis Court		A-2	
<b>DATE</b> Nov 22-65		<b>PURPOSE</b> Make termite repairs to dwelling			
		<b>OWNER</b> E. Chew same			
<b>ZONE</b> R-1		<b>ARCH'T</b>			
		<b>CONT'R</b> Valley Termite		1617-18th St. 448-1882	
<b>VAL.</b> \$400.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME SHEET ROCK</b>	12-2-65	Court			
<b>FINAL</b>	12-7-65	<i>[Signature]</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS

**COMPLETE  
AND OK**

**INSPECTOR**