

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>6840</i>		LOCATION <i>776 Atherton Blvd</i>			
DATE <i>9/5/30</i>		PURPOSE <i>Sign</i>		PHONES	
ZONE <i>Home Retail</i>		OWNER <i>Systematic</i>			
		ARCH'T			
		CONT'R <i>Wentley Electric</i>			
VAL.	<i>150</i>	STORIES	ROOMS	APTS.	SIZE
Steel Tested by		Elevator Shafts			
Cement Tested by		Boiler Rooms			
Owner's Inspector Rfd. Conc.		Sprinkler System			
		Floor Tests			
Fire Escapes					
Stand Pipes					

1. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 2. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 3. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 4. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 5. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 6. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 7. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 8. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 9. Building Department, City of New York, 100 City Hall, New York, N.Y.  
 10. Building Department, City of New York, 100 City Hall, New York, N.Y.

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="302 833 450 875"><b>COMPLETED AND O.K.</b></p> <p data-bbox="1061 854 1196 880"><b>INSPECTOR</b></p>