

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

<b>PERMIT NO.</b> B-35214	<b>LOCATION</b> 5916 Tahoe Way			
<b>DATE</b> 5-9-52	<b>PURPOSE</b> Erect dwlg and garage			
<b>ZONE</b>	<b>OWNER</b> B. C. Walden			
	<b>ARCHT.</b>			
	<b>CONTR.</b> Owner			
<b>VAL.</b> \$5,712.00	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>		
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>		
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>		
<b>LATH</b>		<b>GAS VENTS</b>		
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>		
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>		

DATE	CONDITION OF WORK-REMARKS
5-27-52	James. P. E. Curtis
7/25/52	Stucco Nice Insp. (#2 Shingles to be corrected) A. E. Duchino
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>