

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-24994</i>	LOCATION <i>2695 Riverside Blvd.</i>			
DATE <i>4-12-49</i>	PURPOSE <i>Erect Service Station</i>			
ZONE	OWNER <i>Union Oil Co.</i>			
	ARCH'T.			
	CONTR. <i>C. Norman Peterson</i>			
VAL. <i>\$9000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK--REMARKS
4/25/19	Partial Form Insp O. E. Buckius
4/29/19	Form " "
	COMPLETE AND O. K. INSPECTOR