

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-13180</i>	LOCATION <i>1123 - 3rd St.</i>
DATE <i>2/1/45</i>	PURPOSE <i>General repairs to kitchen.</i>
ZONE	OWNER <i>Mr. Clatchy Realty Co.</i>
	ARCH'T.
	CONT'R. <i>J. F. Reynolds</i>

VAL. *195<sup>00</sup>*

STORIES

ROOMS

APTS.

SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
2/1/45	<p>2<sup>ND</sup> FLR. Frame for Laboratory Bldg &amp; Remodeled  Kitchen of Restaurant. All old T &amp; G Wood  work behind Range removed and Ceiling  purred down as "suspended Ceiling". Will provide  ventilating and rear stairs for 2<sup>ND</sup> Exit. R.W. Campbell</p>
COMPLETE AND O. K.	INSPECTOR