

217-7106

| BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD |          |                                  |                 |                     | \$22.00 |
|--|----------|----------------------------------|-----------------|---------------------|---------|
| TYPE BUILDINGS                                       |          |                                  |                 |                     |         |
| PERMIT NO.<br>F-7372                                 | LOCATION |                                  |                 | 649 - Santa Ana Way | A-7     |
| DATE<br>May 18-67                                    | PURPOSE  | Repair fire damage to dwelling   |                 |                     |         |
| ZONE   | OWNER    | Constance Ferguson same          |                 |                     |         |
|  | ARCH'T   |                                  |                 |                     |         |
|  | CONT'R   | Saggs-Werbke 1915-S St. 489-2894 |                 |                     |         |
| VAL. \$4,500.  | STORIES  | ROOMS                            | APTS.           | SIZE                |         |
| INSP.  | DATE     | BLDG. TYPE                       | OCCUPANCY GROUP | PHONE (O) (C)       |         |
| FORM   |          |                                  |                 |                     |         |
| JOIST  |          |                                  |                 |                     |         |
| FRAME  | 6-1-67   | Callaway                         |                 |                     |         |
| SHEET  | 6-5-67   | Pinto                            |                 |                     |         |
| ROCK   |          |                                  |                 |                     |         |
| FINAL  | 7-5-67   | Pinto                            |                 |                     |         |

| DATE   | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------|--------------------------------------|
| 1-3-67 | Pt. of work - not by [Signature]     |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |
|        |                                      |

COMPLETE  
AND OK

INSPECTOR