

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4694</i>	LOCATION <i>408 - San Antonio Way</i>			
DATE <i>8/17/31</i>	PURPOSE <i>Erect new double garage</i>			
ZONE <i>2-Fam</i>	OWNER <i>Plein Realty Co.</i>			
	ARCH'T. <i>Plein Realty Co.</i>			
	CONT'R. <i>Plein Realty Co. 807-f</i>			
VAL. <i>3500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>1000⁰⁰</i>
VENT SHAFTS	BOILER ROOMS	<i>@ 350</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
8/21-	1 st Jump Form on Printer
9-16-36	2 " Frame on Printer
9-18-36	3 " Int. Lph. & Printer

COMPLETE
AND O. K.

INSPECTOR