


2211 7539

BUILDING DIVISION -- BUILDING INSPECTOR'S REPORT CARD \$5.00

TYPE BUILDINGS

PERMIT NO. S-5213		LOCATION 2426 - Del Paso Blvd.		A-6	
DATE Mar 9-67		PURPOSE Const. sign Class E-1			
ZONE C-2		OWNER Maxines		same	
		ARCH'T			
		CONTR Ad-Art		Box 2308 922-5671	
VAL \$100.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET					
ROCK					
FINAL	3-11-68				

1. This form is to be filled out by the building inspector. 2. The building inspector should check the building for compliance with the building code. 3. The building inspector should check the building for safety. 4. The building inspector should check the building for health. 5. The building inspector should check the building for fire. 6. The building inspector should check the building for electrical. 7. The building inspector should check the building for plumbing. 8. The building inspector should check the building for mechanical. 9. The building inspector should check the building for structural. 10. The building inspector should check the building for other.

4.17

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<p data-bbox="275 828 396 880">COMPLETE AND OK</p> <p data-bbox="1075 854 1202 880">INSPECTOR</p>