

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD
TYPE BUILDINGS

PERMIT NO.	LOCATION		
<i>8721</i>	<i>2219 Portola W</i>		
DATE	PURPOSE	PHONES	
<i>10/9/21</i>	<i>Add Front Porch Garage, Floor & Ceiling</i>		
ZONE	OWNER	ARCH'T	
<i>2A</i>	<i>H R Engentr</i>		
	CONT-R		
	<i>Arnold & Frank</i>		

VAL.	STORIES	ROOMS	APTS.	SIZE
	<i>102</i>			

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="330 882 512 935">COMPLETE AND O.K.</p> <p data-bbox="1205 904 1395 935">INSPECTOR</p>