

1930 Glenrose Avenue

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
6-18-75	Bldg. \$450	C-4582 \$10.	Pest Damage REpair Dwelling	Robert Gloyd ✓	Safeguard Pest Cont P.O.Box 618 Carm	Loren	7-18-75
7-16-75	B.E.\$200	C-5451 \$7.50 F6402	Code Comp correction F.H.A. Dwelling	Rory Husted	Owner	Crowler Larsen Larsen	8-1-75 8-1-75 8-1-75
7-22-75	Bldg. \$300	C-5668 \$10.	Reroof	Rory Husted	Owner	Larsen	8-1-75
8/20/75	P. \$500,	C-6626 \$10.	Replace sewer line Dwlg.	Rory Husted	Jack & Jim Sewer Ser. 1035 Rd.	Nystrom	8/25/75

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
C-4582	R 416 F 612	C-6626	R 423 F 354		
		C-6626	R 424 F 051		
C-5451	R 420 F 098				
C-5668	R 420 F 406				
C-5451	R 422 F 188				
C-5668	R 422 F 188				

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 1930 Glenrose Avenue				INSPECTION AREA 6	
LEGAL DESCRIPTION							
BUILDING BY							
DATE							
TITLE AND NAME							
ADDRESS							
ZIP							
CITY-LIC. NO.							
TEL. NO.							
ELECTRICAL BY							
DATE							
GEN. CONTR.							
ELEC. CONTR.							
PLBG. CONTR.							
MECH. CONTR.							
ARCH. ENGR.							
OWNER							
CONST. LOAN LENDER							
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT		NO. OF STORIES	
ROOF CONSTR.		AREA 1st FLOOR		TOTAL AREA		C.S.D.	
EXISTING BLDG'S SAME LOT		C.I. CASE		CENSUS TRCT. NO.			
SIDE YARDS		REAR YARDS		SET BACK REQ.		USE ZONE	
PARK'G REQ.		SPACES		TREES RMVD.		EXISTING BLDG'S SAME LOT	
HOW USED							

NATURE OF WORK:-

PERMIT NO. S.P. -	MICROFILM RECORD		
ISSUED BY			
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO. -	FRAME NO. -
VALUATION	INSPECTION RECORD	REEL NO. -	FRAME NO. -
R.D.F. FEE	JOB FILE	REEL NO. -	FRAME NO. -
S.M.I. FEE			
PLAN CK. FEE			
SEWER INCL. FEE			
PERMIT FEE			
TOTAL FEES	REMARKS AND/OR VARIANCES		

Dwelling