

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No Charge</i>	LOCATION <i>1 ac't of Dry Rd No 48 SANTA YNEZ WAY</i>	
DATE <i>3/31</i>	PURPOSE <i>Make Repairs to Ext. Plastering & front porch</i>	PHONES
ZONE <i>2-family</i>	OWNER	ARCH'T
VAL.	STORIES <i>1</i>	ROOMS
	APTS.	SIZE
CONT-R <i>W. E. TRUESDALE</i>		
Light Shafts		Elevator Shafts
Vent Shafts		Boiler Rooms
Owner's Inspector		Sprinkler System
Lath		Gas Vents
Fire Escapes		Chimneys
Stand Pipes		Skylights

DATE	CONDITION OF WORK-REMARKS
3/2/31	Made Preliminary Insp of Repairs being made to exterior plastering near foundation ^{WOOD} affected now done not. Also returned to Frank Brock
3/5/31	2nd Insp. From Fri " OK Ad Campbell
3/6/31	3 RD " EXT. WTL " OK Ad Campbell
COMPLETE AND O.K.	INSPECTOR