

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4509</i>	LOCATION <i>2778-13^{1/2} Street</i>
DATE <i>6/30/36</i>	PURPOSE <i>Erect new Res. garage</i>
ZONE	OWNER <i>J. C. Ingler</i>
	ARCH'T.
	CONTR. <i>Frank Bldg. Co.</i>

VAL. <i>5500⁰⁰</i>	STORIES <i>2</i>	ROOMS <i>16</i>	APTS.	SIZE <i>Reeplan</i>
-------------------------------	---------------------	--------------------	-------	------------------------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	BOILER ROOMS	<i>1582⁰¹</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 3.00</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
9/30/36	1 ST /NSP. Frame in place. OK R. Campbell
10/15/36	2 ND /NSP. Frame in place. OK R. Campbell
10/26/36	3 RD /NSP. HT LTR. throughout mt. OK R. Campbell <small>NOTE: Cover used 5/16" Grip Lath</small>

COMPLETE
AND O. K.

INSPECTOR