

*R 2466 F 597*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> G-4423	<b>LOCATION</b> 516 - San Miguel Way A-1 (3)
<b>DATE</b> Aug-15-69	<b>PURPOSE</b> Repair pest damage to dwelling
<b>ZONE</b> R-1	<b>OWNER</b> George Mower Same
	<b>ARCH'T</b> 446-7821
	<b>CONT'R</b> Orchard Supply Co. 1731 - 17th Street

<b>VAL.</b> \$300.	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
--------------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>	<i>8-19-69</i>	<i>Residential</i>		
<b>JOIST</b>				
<b>FRAME</b>				
<b>SHEET ROCK</b>				
<b>FINAL</b>	<i>9.4.69</i>	<i>[Signature]</i>		

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>