

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>Jr 5161</i>	LOCATION <i>1420 - 9th St.</i>			
DATE <i>10/28/38</i>	PURPOSE <i>alteration to Terrace Room</i>			
ZONE	OWNER <i>Stobich, J. Day</i>			
	ARCH'T.			
	CONTR. <i>Walter M. Pienk</i>			
VAL. <i>500.00</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
11/15/36	2 nd / HSP. Frame for Furnace Room. ^{O.K.} R.H. Campbell
12/18/36	3 rd / HSP. INT. LATH both sides ceiling of furnace room. Also lathed division wall on South Store with 3/8" Rock Lath ^{O.K.} R.H. Campbell

COMPLETE
AND O. K.

INSPECTOR