

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 8614 Fairbrook Way		INSPECTION AREA I	
LEGAL DESCRIPTION Lot 342 Glenbrook #4					
TITLE AND NAME		ADDRESS			
GEN. CONTR.		Same			
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER		2777-Alvarado St. San Leandro, Calif.			
CONST. LOAN LENDER					
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOMS	AREA 1st FLOOR
					494 gar.
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES
			1	5	1,232 sq. ft.
EXISTING BLDG'S SAME LOT		HOW USED			
BLDG. AREA	C.S.D.	C.I. CASE	ISSUED BY		
DATE	DATE	DATE	DATE		
ELECTRICAL BY		363-7315			
PLUMBING BY					
MECHANICAL BY					
CERTIFICATE OF OCCUPANCY					
ISSUED BY		Calloway			
DATE		5/3/67			

NATURE OF WORK:- Const. dwelling & att. garage Plan 404

PERMIT NO. S.P. - F-5758		ISSUED BY	
ISSUANCE DATE		10/31/66	
VALUATION		\$ 12,400.00	
R.U.F. FEE		\$	
S.M.I. FEE		\$	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$ 46.00	
TOTAL FEES		\$	
MICROFILM RECORD			
PLANS AND APPLICATION		REEL NO. 206	FRAME NO. 045
INSPECTION RECORD		REEL NO.	FRAME NO.
JOB FILE		REEL NO.	FRAME NO.
SEWER INCL. FEE		B498P208-100	
REMARKS AND/OR VARIANCES			
DWELLING			