

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS *916 Vallejo Way*

|                              |                                     |                             |                   |
|------------------------------|-------------------------------------|-----------------------------|-------------------|
| PERMIT NO.<br><i>4415</i>    | LOCATION<br><i>57 Riverside Ter</i> | 916 Vallejo Way             |                   |
| DATE                         | PURPOSE<br><i>Remodelling</i>       | ROOMS<br><i>5</i>           | APTS.<br><i>1</i> |
|                              | OWNER<br><i>John ...</i>            | PHONE                       |                   |
| RECEIVED                     |                                     |                             |                   |
| AUG 20 1928                  |                                     |                             |                   |
| SACRAMENTO BUILDING DIVISION |                                     |                             |                   |
|                              | STORIES<br><i>2</i>                 | SIZE<br><i>30 x 30 - 22</i> |                   |

**ISSUED**  
AUG 20 1928  
SACRAMENTO  
BUILDING DIVISION

| FOUNDATION | STORY             | BSMT | 1 | 2 | 3 | ROOF |                  |               |
|------------|-------------------|------|---|---|---|------|------------------|---------------|
| Ex Wall    | Joints            |      |   |   |   |      | Chimneys         |               |
|            | Beams and Girders |      |   |   |   |      | Fire Place       |               |
|            | Studs and Columns |      |   |   |   |      | Gas Water Heater |               |
| Int Wall   | Bridging          |      |   |   |   |      | Heater Closet    |               |
|            | Fire Stops        |      |   |   |   |      | Furnace          |               |
| Piers      | Fire Escape       |      |   |   |   |      | Boiler Room      | Window Courts |
|            | Stand Pipes       |      |   |   |   |      | Elevator Shaft   |               |
|            | Metal Lath        |      |   |   |   |      |                  |               |
|            | Stairs            |      |   |   |   |      |                  |               |

| DATE    | CONDITION OF WORK—REMARKS                                 |
|---------|---|
| 8/21/29 | 1 <sup>st</sup> Insp. Forms in place OK R.H. Reuter       |
| 7/26/29 | 2 <sup>nd</sup> Insp. Forms " " " R.H. Reuter             |
| 10/2/29 | 3 <sup>rd</sup> Insp. INT & EXT DATA " " R.H. Campbell    |
| 8/9/30  | 4 <sup>th</sup> Insp. House Completed OK R.H. Campbell    |
| 8/9/30  | ISSUED CERTIFICATE OF OCCUPANCY                           |
| 8/9/30  | Street Cleaned up OK R.H. Campbell                        |
| 8/9/30  | COMPLETED<br>AND O. K. <i>R.H. Campbell</i><br>INSPECTOR. |