

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-1044</i>	LOCATION <i>3401-21st Ave</i>			
DATE <i>10/12/33</i>	PURPOSE <i>Alterations & repairs to fire loss</i>			
ZONE <i>Gen Com</i>	OWNER <i>E. H. Trayler, (Agent)</i>			
	ARCH'T <i>Yoko & Reader</i>			
	CONT-R <i>1</i>			
VAL. <i>1000</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
10/2/33	Made Partial Frame Inspection on Fire Damage to 2 nd Story and Roof on 2 Story Store Bldg with rooms above (formerly known as Daily Hall) W. Campbell
10/18/33	2 nd / ASP Frame for New Roof ^{OK} W. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>