

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|----------|------------------------------|----------------------------------|--|---------------------------|--------------------------------------|--------------|-------------------|
| 11/24/76 | E. \$ 100.00 | D-9284 \$ 20.00 <i>G 7319</i> | 30 amp-220 Vac Dryer service to Dwlg | Mr. Gobler Same | Astro Sonics 2318 J Street. | <i>White</i> | <i>12/2/76 E</i> |
| 11/9/65 | B. \$ 400.00 | F-2259 \$ 5.00 | Repair termite damage to dwelling | A. E. Gobler Same | Valley Termite 1617 18th St. | Court | 11/17/65 |
| 12/2/76 | E. \$ 370.00 | D-9416 \$ 20.00 <i>F 7342</i> | Duplex meter service panel-Elect service change -100 amp (1) 50 amp Duplex | Kingsly McCanber Same | John Radu 5260 North Park Way | <i>White</i> | <i>12/10/76 E</i> |
| 3/3/77 | P. \$ 250.00 | E-1534 \$ 20.00 | Replace 50 gal water heater-Dwlg | Mr. Macomber Same | Sacto Plumbing 210 North 12th St. | <i>Seill</i> | <i>3/24/77 P.</i> |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|---------------|-----------------------------|------------|---------------------|------------|---------------------|
| D-9284 | <i>R 464 F 020</i> | | | | |
| ?F-2259 | <i>R 180 F 569</i> | | | | |
| F-2259 | <i>R 464 F 504 - (conv)</i> | | | | |
| D-9416 | <i>R 464 F 504</i> | | | | |
| <i>D-9416</i> | <i>R 466 F 065</i> | | | | |
| <i>D-9284</i> | <i>R 466 F 065</i> | | | | |
| E-1534 | <i>RA 74 F 507</i> | | | | |
| <i>E-1534</i> | <i>RA 76 F 452</i> | | | | |

Seill
RA
Seill

