

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>03-448</i>	LOCATION <i>1379-Jennings Way.</i>			
DATE <i>4/27/38</i>	PURPOSE <i>Erect new dwg.</i>			
ZONE <i>2-Fam.</i>	OWNER <i>Wm. Murcell</i>			
	ARCH'T.			
	CON'TR. <i>Owner</i>			
VAL. <i>4600</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5/11/38	1 ST / MSP. Form in place ^{OR} A W Campbell
6/1/38	2 ND / MSP Frame in place ^{OR} A W Campbell
6/10/38	3 RD / MSP. Int. Lins. Contractors used 1/2" Sheet Rock for Walls & Ceiling ^{OR} A W Campbell
	<p data-bbox="299 850 424 888">COMPLETE AND O. K.</p> <p data-bbox="1138 868 1271 891">INSPECTOR</p>