

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>M. C. 17</i>	LOCATION <i>1017-3^{1/2} St.</i>
DATE <i>SEP 15 1927</i>	PURPOSE <i>Plum Repair</i>
ISSUED SEP 15 1927	OWNER <i>A. J. ...</i>
	ARCH'T <i>J. Gatti</i>
SACRAMENTO CONTR BUILDING DIVISION	

<i>100</i>	STORIES	ROOMS	APTS.	SIZE
------------	---------	-------	-------	------

Steel Tested by	<i>OK</i>	Elevator Shafts
Cement Tested by		Boiler Rooms
Owner's Inspector Rfd. Conc.		Sprinkler System
Fire Escapes		Floor Tests
Stand-pipes		

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="202 874 346 919">COMPLETED AND O. K.</p> <p data-bbox="1042 899 1137 919">Inspector</p>