

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

§3

| | | | | | |
|----------------------|--------|---|-------|-------|------|
| PERMIT NO. C-4999 | | LOCATION 1005 Front Street | | | |
| DATE Aug 30/56 | | PURPOSE Repair truck damage to birck column | | | |
| ZONE | | OWNER Mrs. Friedman | | | |
| | | ARCH'T | | | |
| | | CONTR McMillan and Pierce GI32662 | | | |
| VAL. | 450 | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | INSPECTOR | | | |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME | | | | | |
| LATH | | | | | |
| FINAL | 1-9-57 | <i>[Signature]</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|--------------------|------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |