

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. 8722 d	LOCATION 258 <del>1st</del> 31/30 Vernado Ave 2815 Santa Cruz	PURPOSE	PHONES
DATE 7/6/31	OWNER Rustin 1814 4th St, 9007	ARCHT	
ZONE A-1	CONT-R		

VAL. 1500	STORIES 1	ROOMS 4	APTS. 1	SIZE 24x24-20
--------------	--------------	------------	------------	------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
12/4/31	2 <sup>ND</sup> Jump Frame of P.H. Dues
	COMPLETE AND O.K. <span style="float: right;">INSPECTOR</span>