

Lot # 346		BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD			\$41.00
Northgate #3		TYPE BUILDINGS <sup>587 7389</sup> <sub>R 86 778-783</sub>			
PERMIT NO. D-9333	LOCATION 628 W. El Camino Avenue A-2				
DATE 8-10-61	PURPOSE Const. dwlg. & gar. Plan # 101				
ZONE R-1	OWNER Cowal Const. P.O. Box 2629 Sacto.				
	ARCH'T				
	CONT'R Owner Same WA 7-1121				
VAL. \$14,300	STORIES 1	ROOMS 6	APTS.	499 gar.	SIZE 1488 sq. ft.
INSP.	DATE	INSPECTOR			
FORM	8-14-61	Calloway			
JOIST	8-22-61	Fuller			
FRAME	10-17-61	Fuller			
LATH	2-15-62	J. Barbato			
FINAL	3-23-62	J. Barbato			

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
8-21-61	<del>Pr. Jans</del> missing seals. no cold blocking between 4x6 girders Jans
10-13-61	Pr. Jans. So many corrections to write up Fuller
1-12-62	Pr. : W. H. King. 5 F. 1/16" 2 Bechtel Bechtel
1-16-62	Bed tray removed & corrections made
3-14-62	Pr. Jans - Hole in fire wall of gm light Jans
	COMPLETE AND OK

INSPECTOR