

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5170</i>	LOCATION <i>1831-4th Ave</i>
DATE <i>10/31/36</i>	PURPOSE <i>Erect new duplex area</i>
ZONE	OWNER <i>Robert & Thelma Frize</i>
	ARCH'T.
	CONT'R. <i>John Fernandez</i>

VAL. <i>5600⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>8</i>	APTS.	SIZE <i>Duplex</i>
-------------------------------	------------------	----------------	-------	-----------------------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS <i>Area</i>
OWNER'S INSPECTOR	SPRINKLFR SYSTEM <i>1600⁰¹</i>
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK-REMARKS			
11/6	10	Jump	Frames 9K	Purter
12-8	2	"	Frame .1	Purter
12-14	3	"	Lath .2	Purter

COMPLETE
AND O. K.

INSPECTOR