

Let 4		BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$36.00			
Carella Gardens #3 <i>amir</i>		TYPE BUILDINGS		A-73 E-409-H16	
PERMIT NO.	D-6399	LOCATION	7443 Sylvia Way		A-5
DATE		PURPOSE Const dwelling and garage			
Jul 29 60	ZONE	OWNER	Peter J. Mc Murray		
R-1	ARCH'T	OWNER 7251-15th St. GA 1-5313			
VAL.	12,900.	STORIES	ROOMS	APTS.	487 GAR. SIZE 1364 S. F.
		1	5		
INSP.	DATE	INSPECTOR			
FORM	8-3-60	Court			
JOIST	8-26-60	Barloto			
FRAME	9-30-60	Fuller 1-15-63 <i>noted in gas</i> <i>noted in gas</i>			
LATH	10-5-60	Fuller			
FINAL	1-22-63	Riolo <i>noted sent 11-21-62 Am</i>			

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
9-27-60	P.T. 1. Knee plate not in. 2. Shingles not all in. 3. Passway brass in garage. 4. Garage floor encroached. 5. Sillid to cutting & blocks top of fire wall. <span style="float: right;">Fletcher</span>
10-5-60	PT Not ready - Fletcher
11-16-60	PT Rails in garage fire wall not spotted. Fletcher
5-2-61	PT. Fire separation not completed. Badette
1-8-62	PT Work in yard. Fire wall not complete. Inspection slip in inspector file. <span style="float: right;">Callaway</span>
1-18-62	PT Fire wall not complete. Callaway
5-31-62	Accepted. You are living there.
11-9-62	Facts Survey & Callaway Inspection without a final find. COMPLETE AND OK Give notice to Facts Survey & Callaway <span style="float: right;">INSPECTOR</span>

Lot 4 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$36.00					
Carella Gardens #3			TYPE BUILDINGS		Card #2
PERMIT NO.					
D-6399		LOCATION 7443 - Sylvia Way		A-5	
DATE		PURPOSE Const. dwlg. & gar.			
Jul 29-60		OWNER Peter J. McMurray 7251 - 15th St.			
ZONE		ARCH'T			
R-1		CONT'R Owner		Same GA 1-5313	
VAL. \$12,900.		STORIES 1	ROOMS 5	APTS.	487 gar. SIZE 1,364 sq. ft.
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL					

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-11-62	<p>Dr. SR on ground not covered.          LB does not extend to corners          or ground. Drilling is broken</p>
1-11-63	<p>Couldn't locate the street photo</p>
1-14-63	<p>Brickwork needs repair on east          of dwg. street work needs enclosing          in gas. Entering ground. Rugs in          closet</p>
1-22-63	<p>Photo</p>
	<p>COMPLETE          AND OK</p> <p style="text-align: right;">INSPECTOR</p>